

TENSILITY

Product Change Notification
PCN Issue Number: 00109


Date: 12/20/2021

Product type: M12 A-code connector (8-pin)

Change type: PCB pin alignment holder

Products affected by the change:

54-00248




54-00251



Update: A plastic pin alignment plate has been added to better hold the pin position and improve ease of drop-in-place functionality. See below:

54-00248



54-00251



No change to fit or function is anticipated because of this change. Form is nominally affected by the increased footprint on the PCB but is not expected to interfere with adjacent components.

Please direct all questions regarding this PCN to:

engineering@tensility.com

541-323-3228